










## Model 0645 Plunger Style Mole Trap – Instructions

NOTE: Safety pin should be reinserted whenever un-sprung mole traps are removed from ground.

<p><b>1.</b> To identify active mole tunnels, flatten out all tunnels. Wait 24 hours. Tunnels that resurface are most likely the active tunnels. Set traps in these locations.</p>		<p><b>2.</b> Make a depression in the roof of the main tunnel by pressing down with your thumb.</p>	
<p><b>3.</b> Center the trap on the tunnel, with the trap pan directly over the depression you've made with your thumb.</p>		<p><b>4.</b> Push trap down until spears have bottomed out.</p>	
<p><b>5.</b> Preset spear holes by plunging spears up and down until they travel easily to the bottom on their own.</p>		<p><b>6.</b> Before setting the trap, make sure the firing latch is OUTSIDE the pan.</p>	
<p><b>7.</b> Holding the trap frame in place, rapidly pull upward on T handle until the firing latch snaps over the pan. Ease T handle down until latch catches.</p>		<p><b>8.</b> Trap is set. If necessary, apply slight downward force to ensure pan is fitting IN the thumb depression and is contacting the roof of the tunnel.</p>	
<p><b>9.</b> Trap has fired. Remove mole.</p>			